


SHAD

HONDA CB 750 HORNET '23 H0CB73SR

BCN



1 263261 x1 →
263262 x1 ←

2 261121 x2
Ø20 Ø11 x18

3 303118 x2
Ø10

4 303025 x2
Ø10

5 304067 x2
M10/1,25x50 DIN 961

6 261042 x2
Ø16 Ø9 x15

7 303045 x2
Ø8

8 303027 x2
Ø8

9 304172 x2
M8x70 DIN 7380

WARNING!

GB Do not fully tighten the screws until it is ensured that the KIT is correctly attached and aligned. Check tightness every 4 months.


E No apretar los tornillos del todo hasta asegurarse que el KIT está correctamente colocado y alineado. Repasar apriete cada 4 meses.

D Ziehen Sie die Schrauben nicht ganz fest, bevor Sie sich nicht vergewissert haben, daß der Bausatz korrekt eingestellt und ausgerichtet ist. Alle 4 Monate Drehmoment überprüfen.

I Non stringere del tutto le viti fin tanto non si è sicuri che il kit è collocato correttamente e allineato. Controllare il serraggio delle viti ogni 4 mesi.

F Ne pas serrer les vis avant d'être sûr que le KIT soit correctement positionné et ajusté. Vérifier le serrage des vis tous les 4 mois.

ATTENTION: For a complete assembly of the equipment, assemble the top kit together with the cafe racer.



IMPORTANT: Based on European models. For compatibility with models in other continents, check www.shad.es

WWW.SHAD.ES

REF. 500479 Edition 1ª