



DIFFICULTY LEVEL


SHAD

3P
SYSTEM

BCN

BMW M 1000 XR '25-

W0MX16IF



1 262659 x1 →
262660 x1 ←




2 303045 x16
Ø8



3 303027 x8
Ø8



4 304028 x4
M8 x 25 DIN 7380



5 263903 x1 →
263904 x1 ←



6 304053 x4
M8 x 30 DIN 7380



7 302024 x4
M8



8 304039 x4
M8x40 DIN 7380



9 260648 x2
Ø16 Ø9 x 5

WARNING!



(GB) Do not fully tighten the screws until it is ensured that the KIT is correctly attached and aligned. Check tightness every 4 months.

(E) No apretar los tornillos del todo hasta asegurarse que el KIT está correctamente colocado y alineado. Repasar apriete cada 4 meses.

(D) Ziehen Sie die Schrauben nicht ganz fest, bevor Sie sich nicht vergewissert haben, daß der Bausatz korrekt eingestellt und ausgerichtet ist. Alle 4 Monate Drehmoment überprüfen.

(I) Non stringere del tutto le viti fin tanto non si è sicuri che il kit è collocato correttamente e allineato. Controllare il serraggio delle viti ogni 4 mesi.

(F) Ne pas serrer les vis avant d'être sûr que le KIT soit correctement positionné et ajusté. Vérifier le serrage des vis tous les 4 mois.



IMPORTANT: Based on European models.
For compatibility with models in other continents, check www.shad.es

